

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Date: May 19, 2010

	MAL
Reviewed:	PHM/
iteviewed.	

Mine Name: Tickaboo Stockpile Removal Project	Permit Number: S/017/0050	
Operator Name: Ucolo Exploration	Inspection Date: May 12, 2010	
Inspector(s): Wayne Western	Time: $4:30 - 5:00 \text{ pm}$	
Other Participants: None	Mine Status: ACT	

	Elements of Inspection		Evaluated	Comment	Enforcement
1.	Permits, Revisions, Transfer, Bonds		\boxtimes	\boxtimes	
2.	Public Safety (shafts, adits, trash, signs, h	ighwalls)	\boxtimes	\boxtimes	
3.	Protection of Drainages / Erosion Contro				
4.	Deleterious Material				
5.	Roads (maintenance, surfacing, dust cont	rol, safety)			
6.	Concurrent Reclamation				
7.	Backfilling/Grading (trenches, pits, roads shafts, drill holes)	, highwalls,			
8.	Water Impoundments				
9.	Soils				
10.	Re-vegetation				
11.	Air Quality				
12.	Other				

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The Operator is current on the permit fees and the Division and BLM hold a \$10,000 bond on the 3 acre site. Reclamation of the site will consist of removing the stockpiles and then vegetation.

The site consists of stockpiles of uranium; there are no shafts, adits or highwalls so the public hazards are minimum. There are two uranium ore stockpiles on the west side of the Shootamaring Canyon road and one on the east side. Only the two on the west side are included in the Tickaboo Stockpile Removal NOI. The stockpile on the east side is still included in Ucolo's Ticaboo stockpile removal project S/017/0001.

Uranium prices are currently depressed so the prospect of activity on the site is unlikely until prices improve.

Conclusions and Recommendations:

The Division should continue to monitor the site.

Inspection Date: May 12, 2010 Page 2 of 4 S/017/0050

Inspector's Signature

WHW

cc: Nancy Wolverson, Operator


Buzz Rakow, Hanksville BLM
O:\M017-Garfield\S0170050-TicabooStockpileRemoval\inspections\insp-05122010.doc

Way a tateur


Inspection Date: May 12, 2010 Page 3 of 4 S/017/0050




Loading ramp



Stockpile, limited vegetation on site and no sign of erosion





Stockpile



Picture of stockpile taken from the road